


WIRING DIAGRAM GS2000



WIRING DIAGRAM GS2000 (w/ LOW PRESSURE SWITCH)

